




PRODUCT UPDATE

Air Bleed Filter Orifices

5R110W TorqShift Transmission

The following update has been added to our overhaul kits T136002A and T136002AP, built with date codes of 8/27/2008.

As pictured these filters are located in the rear of the transmission case and the center support and are easily removed with a small punch and hammer and are installed the same way and then staked in place.



These filters can be easily damaged by contamination and heat and should be replaced during the building of this unit.