

Bulletin No. 021107

Jaguar, Mazda, Land Rover, Volkswagen JF506E/5F31J OEM KITS & COMPONENTS



Application

MAZDA	
6S	2003-06
MPV 3L	2002-On
LAND ROVER	
Freelander	2002-On
JAGUAR	
X Type	2002-On
VOLKSWAGEN	
Golf 1.9L	2004-06
GTI 1.8L	2002-05
Jetta 1.8L/1.9L/2.8L	2002-05

Years

2002-On

OEM Kits

- 8465**, OHK for Mazda
- 8466**, OHK for Volkswagen
- 8467**, OHK for Land Rover and Jaguar
- 8465B**, Master Less Steels for Mazda
- 8466B**, Master Less Steels for Volkswagen
- 8467B**, Master Less Steels for Jaguar
- 8467BA**, Master Less Steels for Land Rover
- 8465M**, Master with Steels for Mazda
- 8466M**, Master with Steels for Volkswagen
- 8467M**, Master with Steels for Jaguar
- 8467MA**, Master with Steels for Land Rover

Additional OEM Items

- 183146AA**, ST C/P High Clutch, 3.0mm Thick
- 183146AB**, ST C/P High Clutch, 3.2mm Thick
- 183146AC**, ST C/P High Clutch, 3.4mm Thick
- 183146AD**, ST C/P High Clutch, 3.6mm Thick
- 183150AA**, ST C/P Reverse Pressure, 36 Teeth, 0.141" Thick
- 183150AB**, ST C/P Reverse Pressure, 36 Teeth, 0.150" Thick
- 183150AC**, ST C/P Reverse Pressure, 36 Teeth, 0.157" Thick
- 183150AD**, ST C/P Reverse Pressure, 36 Teeth, 0.165" Thick
- 183154B**, ST Low Reverse Pressure, 10 Teeth, 0.250" Thick
- 183555A**, Reverse Piston, 2002-On
- D183420A**, Solenoid Pack (9 Pcs.) for Jaguar, VW and Land Rover, 2002-On
- D183420B**, Solenoid Pack (9 Pcs.) for Mazda, 2002-On
- D183436A***, OE Speed Sensor, 2002-On

*We strongly recommend the replacement of all 3 internal speed sensors at the time of overhaul because these parts can only be serviced when the transmission is removed from the vehicle and on the bench.

Aftermarket Items

- 32440B**, Filter, All except VW, 2002-On
- 32440C**, Filter for VW, 2002-On