

0000000



PART NUMBER: SK 8L90

SHIFT KIT® Valve Body Repair Kit

Fits 2015-on 8L45, 8L90

Corrects, Prevents, Reduces:

- TCC instability issues/overheated converter
- Secondary regulator circuit VB worm track cracking
- · Loss of converter feed
- Codes P0218 and P0741
- · High line, harsh shifts
- · Low line, soft slipping shifts
- Broken hard parts
- Low cooler flow

Includes:

- Drop-in PR and shuttle valve line-up
- Drop-in TCC regulator valve
- Drop-in S2, S3 and S4 regulator valves
- Oversize converter feed limit valve
- Oversize AFL valve

Requires:

AFL-G2-TK (Tool Kit)



This is the same tool kit used for multiple GM and Ford front wheel drive 6-speed kits, including;

- SK 6F35-G2
- SK 6T70-G2
- SK 6T40-G2
- SK 6T40-G3
- SK 8L90







