



# ***PRODUCT UPDATE***


## **5R110W TorqShift**

### **Delayed Forward Engagement**

The following update has been added to our overhaul kits, built with date codes of 8/27/2007

The current production style sealing rings are a known concern to the technical services, as being the cause of *delayed forward engagement*.

The two solid PTFE sealing rings found in this kit use the same installer and resizing tools as the solid PTFE rings used for the 4L60-E stator support for the reverse input clutch.



The solid PTFE ring ensures the best possible seal in this application as it eliminates the need for oil pressure to snap the ring out against the bore which then creates the seal.